

MotorCheck



Summary



REF: <u>RQL7ZYAW</u> DATE: 16/06/2023 **DEALER: Bridge Classic Cars Ltd**


Vehicle History Check



VOLKSWAGEN GOLF CABRIO GTI WHITE, 1986



Minor issues



All Clear



Description				
VRM	C914JWN	POWER	N/A	
VEHICLE	VOLKSWAGEN GOLF CABRIO GTI	VALVES	N/A	
ENGINE CC	1781 cc	GEARS	4	
ENGINE SIZE	1.8 Litres	0-60 MPH	9 seconds	
FUEL	PETROL	TOP SPEED	108 MPH	
BODY	2 DOOR CONVERTIBLE	LAST V5C	25/06/2022	
TRANSMISSION	MANUAL	DOORS	2	
SEATS	N/A	BODY	CONVERTIBLE	
COLOUR	WHITE	BODY CLASS	CAR	
REG DATE	21/05/1986	TYPE APPROVAL	M1	
VIN	****	WHEEL PLAN	2 AXLE RIGID BODY	
ENGINE NO.	DX119377	BOOT CAPACITY	N/A	
ENGINE CODE	M6DMKUADPHA	REG CURRENT	N/A	

Finance

FINANCE	No
LAST CHECKED ON	16/06/2023

Write Off (MIAFTR)

WRITE-OFF (MIAFTR) No


Condition Alerts

CONDITION ALERT No

Scrapped		
SCRAPPED	No	
VIC	No	

Stolen

STOLEN No



DATE	READING	SOURCE		
Historical Readings				
22/07/2022	50,137 Miles	мот		
20/08/2021	50,000 Miles	DVLA		
09/03/2019	49,868 Miles	мот		
18/05/2018	48,949 Miles	мот		
06/04/2017	47,635 Miles	мот		
31/03/2017	47,609 Miles	мот		
23/03/2016	47,313 Miles	мот		
21/03/2016	47,298 Miles	мот		
15/05/2015	47,000 Miles	DVLA		
01/05/2015	46,568 Miles	МОТ		
28/04/2015	46,554 Miles	мот		
10/06/2013	46,427 Miles	мот		
29/05/2012	45,854 Miles	мот		
28/05/2012	45,852 Miles	мот		
22/07/2011	45,696 Miles	мот		
15/07/2011	45,696 Miles	МОТ		
27/04/2007	45,587 Miles	МОТ		
26/04/2007	45,586 Miles	МОТ		
17/06/2006	45,402 Miles	мот		

Service History

SERVICE HISTORY Request the Digital Service History	for this vehicles
At Risk	
AT RISK	No
Taxi/PSV Check	
Found 1 minor issue	
FOUND ON TAXI/PSV DATABASE	Not Checked

10/07/2023, 10:50

MotorCheck

2023, 10:50		Mote	brCheck	
Recall Check				
Found 1 minor issue				
RECALL OUTSTANDING	Not Checked			
Keepers				
PREVIOUS KEEPERS		8		
AGE		37 years		
AVG KEEPERS FOR AGE		15		
LAST V5C		25/06/2022		
KEEPER	START	FINISH		

KEEPER	START	FINISH	DURATION
Current	25/06/2022	N/A	11 months
8th	31/08/2018	25/06/2022	3 years 9 months
1st - 7th	21/05/1986	31/08/2018	32 years 3 months

Plate Change

Colour Change	r Change
COLOUR CHANGES	
CURRENT COLOUR	

Origin & Use

PRIOR USE	No	ORIGIN	GERMANY
IMPORTED	No	EXPORTED	No
IMPORTED NI	No	EXPORT DATE	N/A
IMPORT DATE	N/A		
ORIGIN	N/A		

Yes
21/07/2023
21/05/1986
01/05/1989

#1 22/07/2022		
Test Date	22/07/2022	
Expiry Date	21/07/2023	
Odometer	50,137 Miles	
Test No.	113789036729	
Refusal Reason	N/A	
Advisory	N/A	
Minor	N/A	

#3 09/03/2019		Fail
Test Date	09/03/2019	
Expiry Date	N/A	
Odometer	49,868 Miles	
Test No.	965654694729	
Refusal Reason	Stop lamp(s) remains on when the brakes are released (4.3.2 (a) (iii)). Offside Windscreen washer provides insufficient washer liquid (3.5 (a)). Offside Front Position lamp not working (4.2.1 (a))	
Advisory	N/A	
Minor	N/A	

#2 09/03/2019		
Test Date	09/03/2019	
Expiry Date	08/03/2020	
Odometer	49,868 Miles	
Test No.	419345287780	
Refusal Reason	N/A	
Advisory	N/A	
Minor	N/A	

#4 18/05/2018		
Test Date	18/05/2018	
Expiry Date	17/05/2019	
Odometer	48,949 Miles	
Test No.	990005979138	
Refusal Reason	N/A	
Advisory	Oil leak ()	
Minor	N/A	

#5 18/05/2018		Fail
Test Date	18/05/2018	
Expiry Date	N/A	
Odometer	48,949 Miles	
Test No.	160304727954	
Refusal Reason	Horn not working (1.6.2a)	
Advisory	Oil leak ()	
Minor	N/A	

#7 31/03/2017 F		Fail
Test Date	31/03/2017	
Expiry Date	N/A	
Odometer	47,609 Miles	
Test No.	211151401868	
Refusal Reason	Parking brake: efficiency below requirements (3.7.B.7). Offside rear brake recording little or no effort (3.7.B.5a). Horn not working (1.6.2a). Offside Front position lamp(s) not working (1.1.A.3b). Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b). Offside rear parking brake recording little or no effort (3.7.B.6a). Nearside Front position lamp(s) not working (1.1.A.3b)	
Advisory	Coolant leak ()	
Minor	N/A	

#6 06/04/2017		
Test Date	06/04/2017	
Expiry Date	05/04/2018	
Odometer	47,635 Miles	
Test No.	733887734554	
Refusal Reason	N/A	
Advisory	Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b). Coolant leak ()	
Minor	N/A	

#8 23/03/2016		
Test Date	23/03/2016	
Expiry Date	22/03/2017	
Odometer	47,313 Miles	
Test No.	429413705869	
Refusal Reason	N/A	
Advisory	N/A	
Minor	N/A	

#9 21/03/2016		Fail
Test Date	21/03/2016	
Expiry Date	N/A	
Odometer	47,298 Miles	
Test No.	349701986290	
Refusal Reason	Offside Headlamp not working on dipped beam (1.7.5a). Windscreen washer provides insufficient washer liquid (8.2.3). Exhaust has a major leak of exhaust gases middle box join (7.1.2). Nearside Registration plate lamp not working (1.1.C.1d)	
Advisory	N/A	
Minor	N/A	

#10 01/05/2015	Pass
Test Date	01/05/2015
Expiry Date	30/04/2016
Odometer	46,568 Miles
Test No.	657031125125
Refusal Reason	N/A
Advisory	N/A
Minor	N/A

MotorCheck

#11 28/04/2015		Fail
Test Date	28/04/2015	
Expiry Date	N/A	
Odometer	46,554 Miles	
Test No.	208358915104	
Refusal Reason	Offside Headlamp not working on dipped beam (1.7.5a). Rear fog lamp not working (1.3.2b). Speedometer cannot be illuminated. (6.7.3). Windscreen washer provides insufficient washer liquid (8.2.3). Fuel cap/sealing device does not fasten securely by positive means (7.2.4b)	
Advisory	N/A	
Minor	N/A	

#12 10/06/2013		Fail
Test Date	10/06/2013	
Expiry Date	N/A	
Odometer	46,427 Miles	
Test No.	649631463130	
Refusal Reason	Offside Front Headlamp aim too far to the left (1.8). Offside Rear Stop lamp remains on when the brakes are released (1.2.1e). Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3). Nearside Front Headlamp aim too far to the left (1.8). Nearside Rear Stop lamp remains on when the brakes are released (1.2.1e). Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)	
Advisory	N/A	
Minor	N/A	

#13 10/06/2013		Pass
Test Date	10/06/2013	
Expiry Date	09/06/2014	
Odometer	46,427 Miles	
Test No.	125191763100	
Refusal Reason	N/A	
Advisory	N/A	
Minor	N/A	

#14 29/05/2012		Pass
Test Date	29/05/2012	
Expiry Date	28/05/2013	
Odometer	45,854 Miles	
Test No.	777550252150	
Refusal Reason	N/A	
Advisory	Offside Suspension arm rubber bush deteriorated bu resulting in excessive movement (2.4.G.2). Offside Sus arm has slight play in a ball joint (2.4.G.2). Nearside Suspension arm rubber bush deteriorated but not res excessive movement (2.4.G.2). Nearside Suspension a slight play in a ball joint (2.4.G.2)	pension sulting in
Minor	N/A	

#13 10/06/2013		
Test Date	10/06/2013	
Expiry Date	09/06/2014	
Odometer	46,427 Miles	
Test No.	125191763100	
Refusal Reason	N/A	

#15 28/05/2012		Fail
Test Date	28/05/2012	
Expiry Date	N/A	
Odometer	45,852 Miles	
Test No.	145779842168	
Refusal Reason	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2). Offside Headlamp aim too low (1.8). Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2). Windscreen washer provides insufficient washer liquid (8.2.3). Offside rear brake recording little or no effort (3.7.8.5a)	
Advisory	Offside Suspension arm has slight play in a ball joint (2.4.G.2). Nearside Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2). Nearside Suspension arm has slight play in a ball joint (2.4.G.2). Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b). Offside Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
Minor	N/A	

#16 22/07/2011		Pass
Test Date	22/07/2011	
Expiry Date	21/07/2012	
Odometer	45,696 Miles	
Test No.	895473201270	
Refusal Reason	N/A	
Advisory	N/A	
Minor	N/A	

#17 15/07/2011		Fail
Test Date	15/07/2011	
Expiry Date	N/A	
Odometer	45,696 Miles	
Test No.	388966691123	
Refusal Reason	Nearside Front position lamp(s) not working (1.1.A.3b) Offside Rear position lamp(s) not working (1.1.A.3b). N Direction indicators not working (1.4.A.2c). Nearside re brake recording little or no effort (3.7.B.5a). Exhaust sy not adequately supported (7.1.1). Offside Front positic lamp(s) not working (1.1.A.3b). Nearside Registration p lamp not working (1.1.C.1d). Offside Headlamp not wo on dipped beam (1.7.5a)	earside ear vstem on ilate
Advisory	N/A	
Minor	N/A	

27/04/2007	
26/04/2008	
45,587 Miles	
483407617141	
N/A	
N/A	
N/A	
	26/04/2008 45,587 Miles 483407617141 N/A N/A

#19 26/04/2007		Fail
Test Date	26/04/2007	
Expiry Date	N/A	
Odometer	45,586 Miles	
Test No.	252416417459	
Refusal Reason	Offside Front Front constant velocity joint gaiter split (2.5.C.1a). Offside Rear Brake hose leaking (3.6.A.1). rea brake application uneven (3.7.B.2)	ar
Advisory	Battery insecure. Offside Rear wheel bearing has slight (2.6.2). Exhaust noisy (7.1.4). Oil leak. Nearside Rear wh bearing has slight play (2.6.2). Exhaust has a minor leak exhaust gases (7.1.2)	neel
Minor	N/A	

#20 17/06/2006		Pass
Test Date	17/06/2006	
Expiry Date	16/06/2007	
Odometer	45,402 Miles	
Test No.	400918966164	
Refusal Reason	N/A	
Advisory	N/A	
Minor	N/A	

Tax & SORN		
Found 1 minor issue		
TAX VALID	N/A	
TAX EXPIRY	N/A	
SORN	Yes	

Valuation

BASIC VALUATION	£0.00
Based On	N/A
Trade Value	£0.00
Forecourt Value	£0.00
Private Value	£0.00

GLASS'S VALUATION

Running Costs

AUTOTRADER VALUATION

TOTAL ESTIMATED	£325	
Road Tax *		£325
Fuel		
Insurance		

ROAD TAX *				
CO2	N/A			
FUEL				
No data available.				
INSURANCE				
Group Rating 1-20		N/A		
Group Rating 1-50		N/A		
Annual Cost Estimate		N/A		

* The standard 12 month VED rate for all registered cars in this band is shown for the purposes of comparison. Note, figures quoted reflect the current rate only, and may be subject to change in the future. Cars with a list price of over £40,000 when new pay an additional rate of £310 per year on top of the standard rate, for five years

Warranty

No warranty information available.

Image Capture

Request Images

Full Name

Mobile Phone Number

REQUEST IMAGES

Notes

No notes.