




# Summary



REF: 9G1PLVSY DATE: 25/01/2024 **DEALER:** Bridge Classic Cars Ltd

# **Vehicle History Check**



FORD FIESTA XR2 WHITE, 1989



### Minor issues

Road Tax and Sorn Flag exists on Tax & SORN

Taxi/PSV Check Not Checked

**Recall Check** Not Checked

# All Clear

Finance

No finance agreement recorded

Mileage Reading No mileage discrepancies

At Risk No risk marker recorded

Write-Offs (MIAFTR) No write-off recorded

**Condition Alerts** No condition alerts

Scrapped Not scrapped, no VIC recorded

Stolen No stolen record

Descript	tion
----------	------

VRM	F278SEV	POWER	96 BHP
VEHICLE	FORD FIESTA XR2	VALVES	N/A
ENGINE CC	1597 сс	GEARS	5
ENGINE SIZE	1.6 Litres	0-60 MPH	8.7 seconds
FUEL	PETROL	TOP SPEED	112 MPH
BODY	3 DOOR HATCHBACK	LAST V5C	24/04/2020
TRANSMISSION	MANUAL	DOORS	3
SEATS	N/A	BODY	натснваск
COLOUR	WHITE	BODY CLASS	CAR
REG DATE	07/04/1989	TYPE APPROVAL	M1
VIN 🚯	#######################################	WHEEL PLAN	2 AXLE RIGID BODY
ENGINE NO.	JS64271	BOOT CAPACITY	N/A
ENGINE CODE	FOBNINMKSBB	REG CURRENT	N/A

# Finance

FINANCE	No
LAST CHECKED ON	25/01/2024

# Write Off (MIAFTR)

WRITE-OFF (MIAFTR) No

# **Condition Alerts**

CONDITION ALERT No


# Scrapped

SCRAPPED	No
VIC	No

# Stolen

STOLEN No

Mileages



DATE	READING	SOURCE	
Historical Rea	Historical Readings		
04/10/2023	72,276 Miles	мот	
06/02/2016	72,109 Miles	мот	
06/08/2010	71,458 Miles	мот	
02/08/2010	71,450 Miles	мот	
22/07/2009	70,905 Miles	мот	
25/06/2009	70,895 Miles	мот	
25/07/2008	70,031 Miles	мот	
27/07/2007	67,406 Miles	мот	
24/07/2007	67,390 Miles	мот	
20/07/2006	66,234 Miles	мот	
04/07/2006	66,233 Miles	мот	
29/06/2005	65,059 Miles	мот	

# Service History

SERVICE HISTORY

Request the Digital Service History for this vehicles

# At Risk

AT RISK

No

# Taxi/PSV Check

Found 1 minor issue

FOUND ON TAXI/PSV DATABASE Not Checked

# Recall Check

Found 1 minor issue

RECALL OUTSTANDING

Not Checked

# Keepers

PREVIOUS KEEPERS	3
AGE	34 years 9 months
AVG KEEPERS FOR AGE	14
LAST V5C	24/04/2020

KEEPER	START	FINISH	DURATION
Current	21/04/2020	N/A	3 years 9 months
3rd	21/04/2020	21/04/2020	1 day
1st - 2nd	07/04/1989	21/04/2020	31 years

# Plate Change

PLATE CHANGES No

# Colour Change

COLOUR CHANGES	No
CURRENT COLOUR	WHITE

# Origin & Use

PRIOR USE	No	ORIGIN	SPAIN
IMPORTED	No	EXPORTED	No
IMPORTED NI	No	EXPORT DATE	N/A
IMPORT DATE	N/A		
ORIGIN	N/A		

мот

MOT VALID	Yes
MOT EXPIRY	03/10/2024
REG DATE	07/04/1989
FIRST MOT DUE	01/04/1992

#1 04/10/2023		Pass
Test Date	04/10/2023	
Expiry Date	03/10/2024	
Odometer	72,276 Miles	
Test No.	525915697492	
Refusal Reason	N/A	
Advisory	N/A	
Minor	N/A	

#3 06/08/2010		Pass
Test Date	06/08/2010	
Expiry Date	05/08/2011	
Odometer	71,458 Miles	
Test No.	760808710278	
Refusal Reason	N/A	
Advisory	Offside Front Shock absorber has a light misting of oil (2.7.3). bad oil leakl. Nearside Rear wheel bearing has slight play (2.6.2). offside door step panel slightly corroded. Offside Front Shock absorber has a slightly reduced damping effect (2.7.5)	
Minor	N/A	

#5 22/07/2009		Pass
Test Date	22/07/2009	
Expiry Date	26/07/2010	
Odometer	70,905 Miles	
Test No.	351503009499	
Refusal Reason	N/A	
Advisory	N/A	
Minor	N/A	

#2 06/02/2016		
Test Date	06/02/2016	
Expiry Date	05/02/2017	
Odometer	72,109 Miles	
Test No.	405160478452	
Refusal Reason	N/A	
Advisory	N/A	
Minor	N/A	

#4 02/08/2010		Fail
Test Date	02/08/2010	
Expiry Date	N/A	
Odometer	71,450 Miles	
Test No.	403114810295	
Refusal Reason	Offside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3). Nearside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)	
Advisory	nearside front end of door step panel is corroded bad oil leakl. Offside Front Shock absorber has a light misting of oil (2.7.3). offside door step panel slightly corroded Nearside Rear wheel bearing has slight play (2.6.2). Offside Front Shock absorber has a slightly reduced damping effect (2.7.5)	
Minor	N/A	

#6 25/06/2009		Fail
Test Date	25/06/2009	
Expiry Date	N/A	
Odometer	70,895 Miles	
Test No.	921576479136	
Refusal Reason	Nearside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3). Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advisory	Offside Front Shock absorber has a light misting of oil (2.7.3). corrosion to nearside and offside front floorpans. Offside Front Shock absorber has a slightly reduced damping effect (2.7.5). corrosion to neaside sill (door opening). Nearside Rear wheel bearing has slight play (2.6.2). nearside rear brake hose unions deteriorated. corrosion to nearside innerwing/bulkhead	
Minor	N/A	

# MotorCheck

#7 25/07/2008		Pass
Test Date	25/07/2008	
Expiry Date	26/07/2009	
Odometer	70,031 Miles	
Test No.	750067908262	
Refusal Reason	N/A	
Advisory	N/A	
Minor	N/A	

#9 27/07/2007		Pass
Test Date	27/07/2007	
Expiry Date	26/07/2008	
Odometer	67,406 Miles	
Test No.	752628207236	
Refusal Reason	N/A	
Advisory	N/A	
Minor	N/A	

#11 20/07/2006		Pass
Test Date	20/07/2006	
Expiry Date	19/07/2007	
Odometer	66,234 Miles	
Test No.	142751806228	
Refusal Reason	N/A	
Advisory	N/A	
Minor	N/A	

#13 29/06/2005		Pass
Test Date	29/06/2005	
Expiry Date	28/06/2006	
Odometer	65,059 Miles	
Test No.	482450785144	
Refusal Reason	N/A	
Advisory	N/A	
Minor	N/A	·

#8 25/07/2008		Fail
Test Date	25/07/2008	
Expiry Date	N/A	
Odometer	70,031 Miles	
Test No.	253597008274	
Refusal Reason	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advisory	N/A	
Minor	N/A	

#10 24/07/2007	Fail	
Test Date	24/07/2007	
Expiry Date	N/A	
Odometer	67,390 Miles	
Test No.	883455507278	
Refusal Reason	Offside Headlamp aim too low (1.8). Offside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3). Nearside Headlamp aim too low (1.8). Nearside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3). Nearside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)	
Advisory	Battery insecure. both door step panels slightly corroded. offside front floor pan slightly corroded. nearside outer sill suspect maybe corroded	
Minor	N/A	

#12 04/07/2006	· ·	ail
Test Date	04/07/2006	
Expiry Date	N/A	
Odometer	66,233 Miles	
Test No.	440715286153	
Refusal Reason	Nearside Rear rear parking brake recording little or no effort (3.7.B.6a). Offside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3). Exhaust emissions carbon monoxide content excessive (7.3.B.1a). Nearside rear brake recording little or no effort (3.7.B.5a). Nearside Rear Braking system leaking (3.6.A.1). Offside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)	
Advisory	near side rear inner sill under car getting weak/corroding, slight corrosion at off side front inner wing	
Minor	N/A	



### Valuation

BASIC VALUATION	
Based On	N/A
Trade Value	£0.00
Forecourt Value	£0.00
Private Value	£0.00

AUTOTRADER VALUATION

GLASS'S VALUATION

# **Running Costs**



<sup>\*</sup> The standard 12 month VED rate for all registered cars in this band is shown for the purposes of comparison. Note, figures quoted reflect the current rate only, and may be subject to change in the future. Cars with a list price of over £40,000 when new pay an additional rate of £310 per year on top of the standard rate, for five years

### Warranty

No warranty information available.

Capture

Request Images		
Full Name		
Mobile Phone Number		
	REQUEST IMAGES	

# FINANCE Finance Initial Check: 25/01/2024 13:48, No Finance 25/01/2024 Private KEEPERS Keepers Initial Check: 25/01/2024 13:48, 3 Previous Keepers found 25/01/2024 Private WRITE-OFF (MIAFTR) MIAFTR Write-off Initial Check: 25/01/2024 13:48, No records found